Case Study: Mitigating Collisions on CAT D10/D11 Dozers

Problem: During mining operations in an open-cut mine, there has been an increase in reversing incidents between several D10 dozers. In one incident, an operator reversed at speed into the side of another dozer. Not only did this cause considerable damage to both pieces of machinery, the significant costs involved with loss of production had run into the hundreds of thousands of dollars.

Solution: APS was approached and tasked with implementing a solution to this issue. APS proposed the install of a heavy-duty close proximity radar system to alert operators of objects or machines in there blind spot. APS was involved throughout the entire process; from system configuration and installation; to training of the operators to ensure competency, operation and maintenance of the radar system.

The system consisted of 2 x LED displays mounted inside the cab for independent left and right rear detection, 2 x Preview Sentry radars were installed on the rear LHS and RHS corners of the dozer. The sensors were configured to a detection area of 6m in length and 2m in width, this was not protrude the outer left and right edge of the dozer blade. So when the operator tracks close to stationary objects such as high walls, stock piles, wind rows, the radar does not detect continuously and cause constant false detections.


Goal: The goal was to achieve a safer and more productive work environment for the operators of the dozer fleet, and to help prevent further collisions from occurring. The solution has been a success and near misses and incidents have been minimized to near zero. APS has also completed training with the dozer operators, and feedback from management and everyone involved agree "the system has created a safer work environment for all operators and staff".

Contact your local APS representative to discuss how we can tailor a solution to meet your needs.





Front of Machine



Outer limits of machines width inline with

blades outer edge

Back of Machine



blades outer edge



Authorised Importer and Master Distributor

APS USA 610 Gateway Center Way, Suites J & K San Diego, CA 92102 USA P: 1 619 263 4164 F: 1 619 263 6814

APS Australia U48 / 9 Vision Street, Wangara, WA 6065 Australia Phone: 61 (8) 9302 2369 Fax: 61 (8) 6305 0047

APS: Singapore Colombia Chile Perú Brasil

